

Check and Go Oxygen Analyzer

HCPCS:



- 3-digit LCD display
- Ultra-light weight & stable
- Maintenance free
- Extended battery life
- Easy calibration
- Auto off

PRODUCTS

	Description
18580	Check and Go Oxygen Analyzer, EA

SPECIFICATIONS

	Description
Accuracy and Linearity	1% of full scale constant temperature, R.H and pressure when calibrated at full scale
Display Range	0.0 - 99.9% Oxygen
Operating Temperature	60° F - 104° F (15° C - 40° C)
Resolution	0.1% Oxygen
Response Time	90% of final value < 15 seconds @ 770 F (25° C)
Warm-up Time	None
Warranty	Limited 2 Year
Weight	Approx 3 oz